



234447

57
2/12/99**U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION REPORT****I. HEADING**

Date: February 12, 1999
Subject: Fairway Surplus Site
East Tawas, Michigan

From: William Simes and Mark Durno, On-Scene Coordinators, Region 5

To: K. Mould, U.S. EPA, OERR, Washington, D.C. FAX
R. Karl, U.S. EPA, Chief ERB, Chicago, IL FAX
L. Nachowitz, U.S. EPA ERB, RS-3, Chicago, IL FAX
J. El-Zein, U.S. EPA ERB, Chief RS-1, Grosse Ile, MI FAX
M. Bensing, U.S. EPA ERB, ESS, Chicago, IL FAX
B. Noble, DRMS, Grand Rapids, MI FAX
R. Skowronek, MDEQ/DWRPD/RPS, Lansing, MI FAX
Ken Coble, MDEQ, Lansing, MI FAX
Mike Jury / Pete Johannes, MDEQ, Saginaw, MI FAX

POLREP: POLREP #10

II. BACKGROUND

SITE ID No: B563	Delivery Order No: 0010 (68-S5-98-02)
Latitude: W44°18'31.5"	Longitude: N83°33'22.8"
CERCLIS No: MID005326673	ERRS No: 28854
Response Authority: CERCLA	NPL Status: non-NPL
Start Date: 11/16/98	Completion Date: N/A
Reporting Period: February 6 – February 12, 1999	

III. SITE DESCRIPTION

See Initial POLREP

IV. RESPONSE INFORMATION**A. Situation****1. Current situation:**

The weather condition during the reported period was cold with temperatures ranging from 20 to 45°F and icy conditions. ERRS continues to gather and stage containers, cylinders, drums, and tanks. The site is divided into 45 sections, with each section composed of 10,000-ft².

2. Removal activities to date:

2/06/99-2/12/99:

ERRS continues to search for and stage empty drums, partially full drums/containers, tires, metal debris, and construction debris. Approximately 320,000 ft² have been cleared of visible contamination/debris. To date, ERRS removed all the tires and containers from the structures. Of the 34 structures on site, 33 structures were demolished. Structure 15 (staging area is for small containers) remains on site to be demolished. All the drums/containers have been sampled. ERRS received preliminary sample results of the disposal samples. The T& D coordinator is arranging for the disposal of the hazardous material on site. ERRS completed loading trucks with non-hazardous debris and scrap metal. The total amount of non-hazardous debris was 7,140 cubic yards of non-hazardous debris and 2,015 cubic yards of scrap metal. ERRS continue to load RCRA empty drums/small container and PPE into the rolloff box. To date 90 cubic yards of RCRA drums/small container and PPE have been transported and disposed of off site. ERRS had dismantled over 24 tanks on site and overpacked and staged 55-gallon drums. The material inside tanks labeled T-2 and T-1 is awaiting disposal approval and will be removed by a vacuum truck. START collected 29 composite samples from the site and is anticipating the preliminary sample results from the earlier samples collected last week (41 samples). START removed the smelt material from the piles that had elevated radiological readings. The material was stored into three 55-gallon drums and the area surveyed. Composite samples were collected and analyzed by the gamma spectroscopy unit on site. START inventoried the radiological switches (400), gauges (11), and parachute ripcords (62) stored in one 55-gallon drum. On 2/8/99, MDEQ conducted a reconnaissance of the site and estimated the tire volume on site. MDEQ radiological division conducted a radiological ground survey of the site and assisted the U.S. EPA in determining the total activities of the radiological material. Additional areas of concern were located and were removed and sampled. START completed the radiological sampling at the site on 2/11/99.

3. Enforcement:

None.

B. Next Steps

ERRS will continue to collect and stage drums, tanks, cylinders, used tires; remove hazardous materials from deteriorated structures (15), which will be demolished; consolidate waste streams; arrange for disposal and transportation of hazardous material, and remove ACM throughout the site. START will complete the site composite samples.

C. Key Issues

The site is experiencing deteriorating weather conditions and snowfall, which is reducing the visibility of containers, cylinders, drums, tanks, and hazards scattered throughout the site. Awaiting sample results for the 48 composite samples collected on 1/18 and shipped 1/20. ERRS extended the completion date to 3/30/99.

V. COSTS

Site Cost through 2/11/99:

Site Groups	Ceiling	Cost to Date	Remaining	Percent Remaining
ERRS (Earth Tech)	\$850,000.00	\$504,267.90	\$345,732.10	40.7%
START (E & E) ^a	\$65,000.00	\$63,144.08	1,855.92	2.8%
U.S. EPA	\$75,000.00	\$54,267.90	\$20,732.10	27.6%
TOTAL	\$990,000.00	621,679.88	\$368,320.12	37.2%

The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor. Other financial data, which the OSC must rely upon, may not be entirely up to date. The cost accounting provided in this report does not necessarily represent an exact monetary figure, which the government may include in any claim for cost recovery.

VI. DISPOSITION OF WASTES

Date	Description	Quantity	Location
12/9/98	Nonhazardous, RCRA-empty drums Crushed, drum carcasses	60 yds ³	Waters Landfill 113755 Sherman Rd. Frederic, MI
12/9/98	Nonhazardous, RCRA-empty drums Crushed, drum carcasses	60 yds ³	Waters Landfill 113755 Sherman Rd. Frederic, MI
1/12/99	Nonhazardous, RCRA-empty drums Crushed, drum carcasses	60 yds ³	Waters Landfill 113755 Sherman Rd. Frederic, MI
1/14/99 – 1/15/99	Nonhazardous, demolition debris	820 yds ³	Whitefeather Development 2401 East Whitefeather Rd Pinconning, MI
1/18/99- 1/22/99	Nonhazardous, demolition debris	2760 yds ³	Whitefeather Development 2401 East Whitefeather Rd Pinconning, MI
1/25/99- 1/28/99	Nonhazardous, demolition debris	1560 yds ³	Whitefeather Development 2401 East Whitefeather Rd Pinconning, MI
2/01/99- 2/04/99	Nonhazardous, demolition debris	1560 yds ³	Whitefeather Development 2401 East Whitefeather Rd Pinconning, MI
2/06/99- 2/12/99	Nonhazardous, demolition debris	1380 yds ³	Whitefeather Development 2401 East Whitefeather Rd Pinconning, MI
1/11/99 – 1/22/99	Nonhazardous, metal debris	675 yds ³	West Branch Scrap Metal West Branch, Michigan
1/25/99 – 1/29/99	Nonhazardous, metal debris	400 yds ³	West Branch Scrap Metal West Branch, Michigan
2/01/99 – 2/05/99	Nonhazardous, metal debris	640 yds ³	West Branch Scrap Metal West Branch, Michigan
2/06/99 – 2/12/99	Nonhazardous, metal debris	300 yds ³	West Branch Scrap Metal West Branch, Michigan